

TEST REPORT

No. : NBIN1911012467SC

Date : Nov 25, 2019

Page: 1 of 3



CUSTOMER NAME: HAINING BOYUMUTONG DECORATION MATERIAL CO.,LTD
ADDRESS: NO.238 WEST QIANJIANG ROAD, HAINING CITY, ZHEJIANG PROVINCE, CHINA

Sample Name : PVC FLOOR TILE
Product Specification : 4mm
Product or Lot No. : Vinyl floor 01

Above information and sample(s) was/were submitted and confirmed by the client. SGS, however, assumes no responsibility to verify the accuracy, adequacy and completeness of the sample information provided by client.

Date of Receipt : Nov 06, 2019
Testing Start Date : Nov 06, 2019
Testing End Date : Nov 25, 2019
Test result(s) : For further details, please refer to the following page(s)
(Unless otherwise stated the results shown in this test report refer only to the sample(s) tested)

Signed for
SGS-CSTC Standards Technical
Services Co., Ltd Ningbo Branch

Luna Yu
Authorized signatory



TEST REPORT

No. : NBIN1911012467SC

Date : Nov 25, 2019


Page: 2 of 3

Summary of Results:

No.	Test Item	Test Method	Result	Conclusion
1	Dimension Stability	ASTM F2199-18	See test result	/

Note: Pass : Meet the requirements;
 Fail : Does not meet the requirements;
 / : Not Apply to the judgment.

Original Sample Photo:



Sample A



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <http://www.sgs.com/en/Terms-and-Conditions.aspx> and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <http://www.sgs.com/en/Terms-and-Conditions/Terms-e-Documents.aspx>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.
 Attention: To check the authenticity of testing / inspection report & certificate, please contact us at telephones: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

SGS-CSTechnical Services Co., Ltd.
 Ningbo Branch Material Laboratory

1-2,5F West No. 4 Building Lingyun Industry Park, No. 1177 Lingyun Road, Ningbo National Hi-Tech Zone, Ningbo, China 315040 t (86-574) 87767006 f (86-574) 87901159 www.sgs.com.cn
 中国·宁波·国家高新区凌云路1177号凌云产业园4号楼西1-2,5层 邮编: 315040 t (86-574) 87767006 f (86-574) 87901159 e sgs.china@sgs.com

TEST REPORT

No. : NBIN1911012467SC

Date : Nov 25, 2019

Page: 3 of 3

Test Item: Dimension Stability

Sample Description: Brown Board

Test Method: ASTM F2199-18

Test Condition:


Heat treatment condition: 82°C, 6h

Recovery condition: (23 ± 2) °C, (50 ± 5) % RH, 24h

Test Result:

Sample	Test Item	Result		
Sample A	Dimension Stability	Curling	Final Curling	0.02mm
			Max Curling	0.02mm
		Dimension Stability	Length Direction	0.04%
			Width Direction	0.03%

Test Photo:



Equipment Information:

Equipment	Model	Equipment No.	Calibration date	Next Calibration date
Precision High Temperature Ventilation Aging Oven	DPH400-300A	NBPL-A011	2019-07-02	2020-07-01

***** End of report*****

